



September 4, 2025

Mr. Kevin Cornick Town of New Windsor 211 High Street New Windsor, MD 21776

Mr. Walter Smith Heidelberg Materials New Windsor 1703 Old New Windsor Road New Windsor, MD 21776

Subject: Report on High Air Overpressure Event - August 29, 2025

Dear Mr. Kevin Cornick and Mr. Walter Smith:

This letter serves to formally notify you of a high air overpressure event that occurred during a blasting operation on Friday, August 29, 2025, at Heidelberg Materials New Windsor Quarry.

An initial review of all documentation and records indicates that the blast was designed and executed in accordance with established rules and safe blasting practices. No deviations from standard procedures were identified.

At this time, preliminary findings suggest the event may have been caused by a mechanical failure, either with the blast box or the detonators. To ensure due diligence, we are conducting a thorough investigation into the cause of this occurrence and will provide timely updates as additional information becomes available.

As a precaution, all blasting equipment utilized in the shot has been quarantined and removed from service until the investigation is complete.


Safety is our top priority. We take this matter very seriously and remain committed to maintaining the highest standards of safety and compliance. Please do not hesitate to contact me if you have any questions or require further information at this stage.

Sincerely,

Toby Forney
Orica Senior Technical Services Engineer

### Legend

- 1) 39.530531, -77.109025
- 39.531103, -77.108411
- 39.529633, -77.111222
- 39.530767, -77.110928
- 39.531503, -77.108333
- 1502 Old New Windsor Rd 0





# Heidelberg Materials - New Windsor, Maryland

Individual Shot Blast Report

Site Name: New Windsor Blast Company: Orica Month/Year: August-2025 Check Box if No Blasting Occurred During the Month Reporting

Date/Time: 08/01/2025 at 12:00:00	^ Shot ID: 25-34	** Location-shot: Level 300							Number of Seismographs Used 9	
Seismograph ID	Distance from Shot Location (ft)	Longitudinal in/sec	Freq (Hz)	Transvers in/sec	e Freq (Hz)	Vertical F in/sec	req (Hz)	Max PPV (in/sec)	Air Blast (dB)	
1430 Hollowell Lane	2,142 ft	33.3 Hz 0	.0575 in/s	10.6 Hz	0.09 in/s	10.6 Hz in/s	0.0875	0.09 in/s	118.6 dB	
1502 Old New Windsor Rd	1,339 ft	26.3 Hz 0	.12 in/s	26.3 Hz	0.0825 in/s	21.7 Hz in/s	0.0775	0.12 in/s	124.2 dB	
1530 Old New Windsor Rd	1,732 ft	35.7 Hz 0	.0925 in/s	31.2 Hz	0.065 in/s	41.7 Hz in/s	0.065	0.0925 in/s	123.9 dB	
1608 Old New Windsor Rd	2,083 ft	35.7 Hz 0	.0625 in/s	27.8 Hz	0.0775 in/s	38.5 Hz in/s	0.0675	0.0775 in/s	123.1 dB	
1318 New Windsor Rd	2,815 ft	14.3 Hz 0	.0425 in/s	26.3 Hz	0.045 in/s	15.2 Hz in/s	0.035	0.045 in/s	98.7 dB	
1408 ONWR 10861	1,841 ft	23.8 Hz 0	.0625 in/s	31.2 Hz	0.05 in/s	35.7 Hz in/s	0.0425	0.0625 in/s	116.9 dB	
1416 New Windsor Rd	1,821 ft	33.3 Hz 0	.18 in/s	38.5 Hz	0.225 in/s	41.7 Hz	0.15 in/s	0.225 in/s	106.4 dB	
1416 Old New Windsor Rd	1,470 ft	23.8 Hz 0	.07 in/s	26.3 Hz	0.115 in/s	22.7 Hz in/s	0.0925	0.115 in/s	121 dB	
1721 Greenwood Church Rd	5,112 ft									

<sup>\*</sup> Highlight HIGHEST recorded ground vibration and air blast that the seismograph instrument records for each individual shot. The permittee should report the HIGHEST ground vibration value (longitudinal, transverse, vertical) that the seismograph instrument records for each individual shot.

Aerial map image with seismograph and shot locations should be submitted with each monthly blast report (map should include legend, north arrow, scale, title, seismograph and shot locations corresponding to date).

<sup>🚧</sup> Location should include orientation of shot within the mines permit limits - example = 3rd bench, northeastern area of quarry, 200 feet deep, etc.

<sup>^</sup> Shot ID # should correlate with the monthly map submitted. (For best results the Shot ID # used should be the numerical day of the month - for example if the shot occurred on 1/21/2015 than the Shot ID # would be 21). The Shot ID # 21 would be entered on the monthly map submitted.

#### (MDE-Blast-Report)

### Heidelberg Materials - New Windsor, Maryland

Individual Shot Blast Report

Site Name: New Windsor Blast Company: Orica Month/Year: August-2025 Check Box if No Blasting Occurred During the Month Reporting

08/13/2025 at 12:00:	00
Seismograph ID	

Date/Time:

^ Shot ID: 25-36

\*\* Location-shot: Level 400

Lat / Long - shot: 39.5311 -77.10841 Weather at Time of the Shot: Partly Cloudy, 87 °F

Number of Seismographs Used:

Seismograph ID	Distance from Shot Location (ft)	Longitudinal Freq (Hz) in/sec	Transverse Freq (Hz) in/sec	Vertical Freq (Hz) in/sec	Max PPV (in/sec)	Air Blast (dB)
1318 New Windsor Rd	2,556 ft	8.6 Hz 0.145 in/s	8.1 Hz 0.11 in/s	7.6 Hz 0.103 in/s	0.145 in/s	108.2 dB
1430 Hollowell Lane	2,198 ft	8.6 Hz 0.148 in/s	8.9 Hz 0.343 in/s	9.8 Hz 0.33 in/s	0.343 in/s	113 dB
1502 Old New Windsor Rd	1,424 ft	12.8 Hz 0.298 in/s	17.2 Hz 0.0875 in/s	18.5 Hz 0.155 in/s	0.298 in/s	121.1 dB
1530 Old New Windsor Rd	1,962 ft	15.6 Hz 0.0625 in/s	21.7 Hz 0.128 in/s	19.2 Hz 0.05 in/s	0.128 in/s	112.4 dB
1608 Old New Windsor Rd	2,320 ft	13.9 Hz 0.0475 in/s	19.2 Hz 0.0775 in/s	25 Hz 0.06 in/s	0.0775 in/s	112.2 dB
1721 Greenwood Church Rd	5,351 ft	6 Hz 0.0475 in/s	4.8 Hz 0.0575 in/s	5.6 Hz 0.04 in/s	0.0575 in/s	99.9 dB
1408 ONWR 10861	1,864 ft	13.5 Hz 0.22 in/s	20 Hz 0.163 in/s	10.4 Hz 0.12 in/s	0.22 in/s	122.5 dB
1416 New Windsor Rd	1,598 ft	22.7 Hz 0.185 in/s	27.8 Hz 0.268 in/s	33.3 Hz 0.133 in/s	0.268 in/s	113.8 dB
1416 Old New Windsor Rd	1,460 ft	13.9 Hz 0.278 in/s	14.3 Hz 0.155 in/s	14.9 Hz 0.245 in/s	0.278 in/s	123.3 dB

<sup>\*</sup> Highlight HIGHEST recorded ground vibration and air blast that the seismograph instrument records for each individual shot. The permittee should report the HIGHEST ground vibration value (longitudinal, transverse, vertical) that the seismograph instrument records for each individual shot.

Aerial map image with seismograph and shot locations should be submitted with each monthly blast report (map should include legend, north arrow, scale, title, seismograph and shot locations corresponding to date).

# Heidelberg Materials - New Windsor, Maryland

(MDE-Blast-Report)

Individual Shot Blast Report

Site Name: New Windsor Blast Company: Orica Month/Year: August-2025 Check Box if No Blasting Occurred During the Month Reporting

Date/Time: 08/18/2025 at 12:00:00 ^ Shot ID:

\*\* Location-shot: Level 200

Lat / Long - shot: 39.52963 -77.11122 Weather at Time of the Shot: Overcast, 75 °F

Number of Seismographs Used:

Seismograph ID	Distance from Shot Longitudinal Freq (Hz) Location (ft) in/sec		Transverse Freq (Hz) in/sec	Vertical Freq (Hz) in/sec	Max PPV (in/sec)	Air Blast (dB)
1721 Greenwood Church Rd	4,416 ft					
1430 Hollowell Lane	1,883 ft	12.2 Hz 0.105 in/s	35.7 Hz 0.108 in/s	26.3 Hz 0.0875 in/s	0.108 in/s	107.1 dB

<sup>🚧</sup> Location should include orientation of shot within the mines permit limits - example = 3rd bench, northeastern area of quarry, 200 feet deep, etc.

<sup>^</sup> Shot ID # should correlate with the monthly map submitted. (For best results the Shot ID # used should be the numerical day of the month - for example if the shot occurred on 1/21/2015 than the Shot ID # would be 21). The Shot ID # 21 would be entered on the monthly map submitted.

1502 Old New Windsor Rd	1,089 ft	45.5 Hz	0.235 in/s	38.5 Hz	0.16 in/s	35.7 Hz in/s	0.2013	0.235 in/s	116.7 dB
1530 Old New Windsor Rd	1,053 ft	45.5 Hz	0.325 in/s	33.3 Hz	0.255 in/s	71.4 Hz	0.34 in/s	0.34 in/s	116.1 dB
1608 Old New Windsor Rd	1,394 ft					į.			
1608 Old New Windsor Rd	1,394 ft	45.5 Hz	0.175 in/s	29.4 Hz	0.15 in/s	55.6 Hz in/s	0.185	0.185 in/s	116.7 dB
1318 New Windsor Rd	3,406 ft	50 Hz	0.03 in/s	41.7 Hz	0.035 in/s	31.2 Hz in/s	0.035	0.035 in/s	102.6 dB
1408 ONWR 10861	2,060 ft	50 Hz	0.0575 in/s	50 Hz (	0.085 in/s	62.5 Hz in/s	0.0625	0.085 in/s	105.9 dB
1416 New Windsor Rd	2,513 ft	38.5 Hz	0.128 in/s	38.5 Hz	0.22 in/s	45.5 Hz in/s	0.225	0.225 in/s	107.4 dB

<sup>\*</sup> Highlight HIGHEST recorded ground vibration and air blast that the seismograph instrument records for each individual shot. The permittee should report the HIGHEST ground vibration value (longitudinal, transverse, vertical) that the seismograph instrument records for each individual shot.

Aerial map image with seismograph and shot locations should be submitted with each monthly blast report (map should include legend, north arrow, scale, title, seismograph and shot locations corresponding to date).

# Heidelberg Materials - New Windsor, Maryland

(MDE-Blast-Report)

Individual Shot Blast Report

Site Name: New Windsor Blast Company: Orica Month/Year: August-2025

Rd

Check Box if No Blasting Occurred During the Month Reporting

Date/Time: 08/27/2025 at 11:59:00	^ Shot ID: 25-37	** Location-shot: Level 250	: Lat / Long - shot: 39.53077 -77.11093		Weather Sunny, 7	at Time of the Shot: 0 °F	Number of Seismographs Used 9	
Seismograph ID	Distance from Shot Location (ft)	Longitudinal F	req (Hz)	Transverse Fin/sec	req (Hz)	Vertical Freq (Hz) in/sec	Max PPV (in/sec)	Air Blast (dB)
1721 Greenwood Church Rd	4,652 ft					5		
1318 New Windsor Rd	3,018 ft	13.9 Hz 0.0	5 in/s	9.4 Hz 0.0	4 in/s	41.7 Hz 0.0325 in/s	0.05 in/s	97.3 dB
1430 Hollowell Lane	1,650 ft	11.4 Hz 0.1	33 in/s	11.9 Hz 0.	128 in/s	10 Hz 0.148 in/s	0.148 in/s	100.9 dB
1502 Old New Windsor Rd	837 ft	21.7 Hz 0.2	93 in/s	20 Hz 0.24	48 in/s	16.1 Hz 0.153 in/s	0.293 in/s	114.6 dB
1530 Old New Windsor Rd	1,263 ft	62.5 Hz 0.1	25 in/s	41.7 Hz 0.	153 in/s	83.3 Hz 0.173 in/s	0.173 in/s	115 dB
1608 Old New Windsor Rd	1,624 ft	45.5 Hz 0.0	9 in/s	50 Hz 0.1	in/s	71.4 Hz 0.128 in/s	0.128 in/s	112.9 dB
1408 ONWR 10861	1,673 ft	14.3 Hz 0.0	65 in/s	38.5 Hz 0.	055 in/s	45.5 Hz 0.075 in/s	0.075 in/s	102.6 dB
1416 New Windsor Rd	2,316 ft	62.5 Hz 0.0	75 in/s	33.3 Hz 0.	.165 in/s	55.6 Hz 0.103 in/s	0.165 in/s	103.4 dB
1416 Old New Windsor	1,093 ft	10.6 Hz 0.1	5 in/s	21.7 Hz 0.	.09 in/s	12.8 Hz 0.138	0.15 in/s	106.4 dB

<sup>\*\*</sup> Location should include orientation of shot within the mines permit limits - example = 3rd bench, northeastern area of quarry, 200 feet deep, etc.

<sup>^</sup> Shot ID # should correlate with the monthly map submitted. (For best results the Shot ID # used should be the numerical day of the month - for example if the shot occurred on 1/21/2015 than the Shot ID # would be 21). The Shot ID # 21 would be entered on the monthly map submitted.

- \* Highlight **HIGHEST** recorded ground vibration and air blast that the seismograph instrument records for each individual shot. The permittee should report the **HIGHEST** ground vibration value (longitudinal, transverse, vertical) that the seismograph instrument records for each individual shot.
- \*\* Location should include orientation of shot within the mines permit limits example = 3rd bench, northeastern area of quarry, 200 feet deep, etc.
- ^ Shot ID # should correlate with the monthly map submitted. (For best results the Shot ID # used should be the numerical day of the month for example if the shot occurred on 1/21/2015 than the Shot ID # would be 21). The Shot ID # 21 would be entered on the monthly map submitted.

Aerial map image with seismograph and shot locations should be submitted with each monthly blast report (map should include legend, north arrow, scale, title, seismograph and shot locations corresponding to date).

# Heidelberg Materials - New Windsor, Maryland

Individual Shot Blast Report

Site Name: New Windsor Blast Company: Orica Month/Year: August-2025 Check Box if No Blasting Occurred During the Month Reporting

Date/Time: 08/29/2025 at 11:59:00	^ Shot ID: 25-38	** Location-shot: Level 400	Lat / Long - shot: 39.5315 -77.10833		at Time of the Shot: oudy, 72 °F	Number of Seis	mographs Used:
Seismograph ID	Distance from Shot Location (ft)	Longitudinal Fred in/sec	(Hz) Transve in/sec	rse Freq (Hz)	Vertical Freq (Hz) in/sec	Max PPV (in/sec)	Air Blast (dB)
1318 New Windsor Rd	2,411 ft	10.4 Hz 0.336	in/s 9.6 Hz	0.295 in/s	8.1 Hz 0.243 in/s	0.336 in/s	112.9 dB
1430 Hollowell Lane	2,162 ft	9.3 Hz 0.263 ii	n/s 8.1 Hz	0.618 in/s	8.6 Hz 0.39 in/s	0.618 in/s	123.9 dB
1502 Old New Windsor Rd	1,414 ft	11.6 Hz 0.528	in/s 11.9 Hz	0.243 in/s	13.9 Hz 0.21 in/s	0.528 in/s	133.7 dB
1530 Old New Windsor Rd	2,037 ft	21.7 Hz 0.208	in/s 8.5 Hz	0.233 in/s	22.7 Hz 0.138 in/s	0.233 in/s	121 dB
1608 Old New Windsor Rd	2,398 ft	17.9 Hz 0.175	in/s 14.7 Hz	0.12 in/s	38.5 Hz 0.11 in/s	0.175 in/s	121.1 dB
1721 Greenwood Church Rd	5,430 ft	4 Hz 0.0825 in	/s 5.6 Hz	0.123 in/s	5.9 Hz 0.07 in/s	0.123 in/s	109.9 dB
1408 ONWR 10861	1,762 ft	14.7 Hz 0.505	in/s 33.3 Hz	0.158 in/s	10.9 Hz 0.17 in/s	0.505 in/s	125.8 dB
1416 New Windsor Rd	1,549 ft	26.3 Hz 0.393	in/s 23.8 Hz	0.59 in/s	41.7 Hz 0.405 in/s	0.59 in/s	130.5 dB
1416 Old New Windsor Rd	1,398 ft	8.9 Hz 0.583 ii	n/s 14.3 Hz	0.248 in/s	16.1 Hz 0.39 in/s	0.583 in/s	132 dB

Aerial map image with seismograph and shot locations should be submitted with each monthly blast report (map should include legend, north arrow, scale, title, seismograph and shot locations corresponding to date).

<sup>\*</sup> Highlight HIGHEST recorded ground vibration and air blast that the seismograph instrument records for each individual shot. The permittee should report the HIGHEST ground vibration value (longitudinal, transverse, vertical) that the seismograph instrument records for each individual shot.

<sup>\*\*</sup> Location should include orientation of shot within the mines permit limits - example = 3rd bench, northeastern area of quarry, 200 feet deep, etc.

<sup>^</sup> Shot ID # should correlate with the monthly map submitted. (For best results the Shot ID # used should be the numerical day of the month - for example if the shot occurred on 1/21/2015 than the Shot ID # would be 21). The Shot ID # 21 would be entered on the monthly map submitted.